

FIG. 1A




FIG. 1B




FIG. 2A




FIG. 2B




FIG. 3A




FIG. 3B




FIG. 4A




FIG. 4B




FIG. 5A




FIG. 5B




FIG. 5C





FIG. 5D

FIG. 6A




FIG. 6B




FIG. 7A




FIG. 7B




FIG. 8A





FIG. 8B

FIG. 8C





FIG. 8D

FIG. 9A




FIG. 9B




FIG. 10A





FIG. 10B






FIG. 11A




FIG. 11B




FIG. 11C




FIG. 11D

FIG. 12A




FIG. 12B

10ms-15POWER CONTROL GROUP




FIG. 12C




FIG. 12D




FIG. 12E




FIG. 13A




FIG. 13B




FIG. 13C

$10ms=15$ POWER CONTROL GROUP
 $x = SFN^m (0 \leq m < 36)$




FIG. 13D




FIG. 14A




FIG. 14B

$10ms=15$ POWER CONTROL GROUP
 $x = SFN \cdot m \quad (0 < m < 36)$




FIG. 14C




FIG. 14D

$10ms=15$ POWER CONTROL GROUP
 $x = SFN * m$ ($0 \leq m < 36$)




FIG. 15A




FIG. 15B




FIG. 15C

0 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

43/48




FIG. 16




FIG. 17A




FIG. 17B




FIG. 18A




FIG. 18B

